



Questions? We're here to help!

plugable.com/products/uga-dp-s

support@plugable.com

ご質問は下記へご連絡ください。 nihongo@plugable.com

© 2021 Plugable Technologies | July 30th, 2021



Plugable USB 3.0 and USB-C to DisplayPort Adapter Quick Start Guide

Guía de inicio rápido | Guide de démarrage rapide |
Guida introduttiva | Kurzanleitung | クイック・スタート・ガイド

**Thank you for your purchase of the Plugable
UGA-DP-S USB 3.0 and USB-C to DisplayPort
Adapter!**


The Plugable UGA-DP-S adapter connects to a computer via a USB 3.0 or a USB-C connection and extends an external DisplayPort monitor up to 3840x2160@30Hz resolutions. 4K resolutions and lower are supported.

In the Box

Graphics Adapter with attached USB 3.0 to USB-C adapter

1. Download and install driver.


Descargar e instalar el controlador.
Télécharger et installer le pilote.
Scarica e installa il driver.
Treiber herunterladen und installieren.
ドライバをダウンロードし、インストールします。
plugable.com/products/uga-dp-s



plugable.com/products/uga-dp-s

2. Connect the adapter to host.

Conectar el adaptador al servidor
Connectez l'adaptateur à l'hôte
Collegare l'adattatore al computer host.
Verbinden Sie den Adapter mit Ihrem Host-PC.
当変換アダプタを、システムに接続します。



3. Connect the monitor.

Conectar el monitor
Connectez le moniteur
Collega il monitor
Verbinden Sie Ihren Monitor.
モニタを接続します。

